

PARKER'S ELECTRICAL NQ

43 Canara St Cranbrook Q 4814
0747288586 0488571866
admin@parkerselectricalnq.com.au
parkerselectricalnq.com.au
LIC No 86114



05 September 2019

Gromac Quarry NQ
Barabon Quarry

Earth Leakage Devices

Date	Plant	Item No	Plant/Location	Test	Re-Test
05/09/2019	GN814		Pit Crusher Generator Main	12ms	05/09/2020
05/09/2019	GN814		Pit Crusher Generator outlets	13ms	05/09/2020
05/09/2019	GN825		Pre-coat Generator Main	21ms	05/09/2020
05/09/2019	Gn825		Pre-Coat Generator Outlets	25ms	05/09/2020
05/09/2019	Oil Container	1	Office	5ms	05/09/2020
05/09/2019	Oil Container	2	Office	10ms	05/09/2020
05/09/2019	Oil Container	3	Office	16ms	05/09/2020
05/09/2019	Post outlet 1	1	Office	10ms	05/09/2020
05/09/2019	Post Outlet 2	2	Office	9.5ms	05/09/2020
05/09/2019	Store Container	1	Office / RCD Replaced	8ms	05/09/2020
05/09/2019	Office sub board	1	Office	23.5ms	05/09/2020
05/09/2019	Office sub board	2	Office	7.1ms	05/09/2020
05/09/2019	Office sub board	3	Office	17ms	05/09/2020
05/09/2019	Office sub board	4	Office	8ms	05/09/2020

All RCD were tested according to the table above and where in good working order except for the Store Container that had a faulty RCD and was replaced. The next test date is 05 September 2020.

Gary Parker